JV300-160 Ver.410r0 SB54-410 S996E540 2025.06.24 10:42

USAGE

SCAN 00010909315 USE TIME 00013678 WIPING 00000306 LENGTH(m) 00103626 AREA(Sqm) 00000166417

HEAD ID

HEAD 1:38C897673908B87869292R04 HEAD 2:3868877748D8B85848F91R0S

SHOT COUNT

H1-A: 01710876298	H1-B: 02488459823	H1-C: 01310711413	H1-D: 01680344123
H1-E: 01683021302	H1-F: 01307442028	H1-G: 02494180222	H1-H: 01708078269
H2-A: 01769625770	H2-B: 02590422944	H2-C: 01386787132	H2-D: 01732895611
H2-E: 01729525823	H2-F: 01388355439	H2-G: 02586985184	H2-H: 01773154107

NOZZLE RECOVERY

H1-A: ---/---/---/---/---/---/---/---/---/---/	H1-B: ---/---/---/---/---/---/---/---/---/---/
H1-C: ---/---/---/---/---/---/---/---/---/---/	H1-D: ---/---/---/---/---/---/---/---/---/---/
H1-E: ---/---/---/---/---/---/---/---/---/---/	H1-F: ---/---/---/---/---/---/---/---/---/---/
H1-G: ---/---/---/---/---/---/---/---/---/---/	H1-H: ---/---/---/---/---/---/---/---/---/---/
H2-A: ---/---/---/---/---/---/---/---/---/---/	H2-B: ---/---/---/---/---/---/---/---/---/---/
H2-C: ---/---/---/---/---/---/---/---/---/---/	H2-D: ---/---/---/---/---/---/---/---/---/---/
H2-E: ---/---/---/---/---/---/---/---/---/---/	H2-F: ---/---/---/---/---/---/---/---/---/---/
H2-G: ---/---/---/---/---/---/---/---/---/---/	H2-H: ---/---/---/---/---/---/---/---/---/---/

INK REPLACE COUNT/ REMAIN / Lot No.

1: 48	2: 308	3: 82	4: 81	5: 45	6: 304	7: 62	8: 62
1: 100	2: 2	3: 28	4: 100	5: 94	6: 2	7: 70	8: 2
1:E1B04072	2:E1B04072	3:E1B04017	4:E1B04017	5:E1B04045	6:E1B04045	7:1215036C	8:1215036C

Entries

Reference No.	Customer name
Installation date	Damage date
Repair date	Last replacement date
RLP Version	MIMAKI Driver version
Dealer name / Country	Name of person in charge of repair
Damaged parts / parts code	Replacement parts / parts code

How the damage occurs

Reason for replacement